

Total Fire Protection 2/20/2024

Issues with fire alarm panel, the old outdoor bell failed to pass inspection a couple times.

Since the new remodel of the discovery history exhibit room, I had Total fire replace the old bell. During this process I have learned that the fire panel might not be capable of upgrading to the new horn and strobe outdoor device. I was also informed today that all the pull stations and smoke detectors and audible devices should be inspected every year. I do know that the auditable devices do work in the museum. However, they need to be inspected by a licensed inspector. I did explain to Ben that I have been with the museum for fifteen years and I have never seen anyone inspect the pull stations and the person that was in my position before me never mentioned anything about the pull stations or left a paper trail that that has been done. Ben will try to have someone at the museum on March 1st to see what needs to be done. I also told Ben I would like to have a list of all inspections that need to be done in accordance with the NFPA standards. If a board member would like to tag along when Total fire comes to do the inspection, please let me know. Sometimes Total Fire will give a date and time and others are just a date they can be here.